

GPOP - Issue Review System

Part Number: 82212043A\$, 82212945A\$

Part Description: Drop in Bedliner

Issue Under-the-Rail Rambox Bedliner CANNOT be installed on MY 2015 Ram trucks
Description: manufactured after January 1, 2015 due to a sheet metal form change.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
