



SUBJECT


Discontinuation of Recall/Service Action Label Use

MODEL

All

SITUATION

As of May 1, 2015, Technical Service will no longer require the use of the round Recall/Service Action label on the B-pillar. After review of technician feedback, it was determined the labels are not required, nor have they been consistently used.



The use of AIR, the Key Reader, and/or the Warranty Inquiry system is the preferred method to determine vehicle Recall status.

Emissions Recall labels are not affected by this change, and will still be used for all emissions Recall Campaigns.

[Copyright ©2015 BMW of North America, Inc.]