

Indian Motorcycle**Indian**
MOTORCYCLE

Team Tips

ARTICLE: I-15-05-02

DATE: 06/02/2015

*Published for Indian Motorcycle Dealerships, Distributors, and Service Technicians***2015 Indian Scout – Accessory Handlebar Improper Finish**

This Team Tip has been released to communicate that some Scout accessory handlebars may have an improper finish. Indian Motorcycles has determined that some Scout accessory handlebars were not polished between the knurled clamp sections in the center of the handlebars.

Dealer should file a part stock warranty claim if they have a set of accessory bars with an unpolished center section.

AFFECTED PART NUMBERS

DESCRIPTION	PART NUMBER
EXTENDED REACH HNDLBR, POLISHED STAINLESS	2880152-410
REDUCED REACH HNDLBR, POLISHED STAINLESS	2880153-410

Please distribute this Team Tip to all dealership personnel.

