



**Countries:** BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, PANAMA

**Document ID:** IK1600183

**Availability:** ISIS, FleetSIS, IsSIR

**Revision:** 13

**Major System:** CAB / SLEEPER / HOOD

**Created:** 5/9/2013

**Current Language:** English

**Last Modified:** 11/28/2016

**Other Languages:** NONE

**Author:** David Smith

**Viewed:** 3356

[Less Info](#)

Hide Details

Coding Information

| Copy Link | Copy Relative Link | Bookmark                              | Add to Favorites | Print | Edit Document | Provide Feedback | Helpful | Not Helpful |
|-----------|--------------------|---------------------------------------|------------------|-------|---------------|------------------|---------|-------------|
|           |                    | <br><a href="#">View My Bookmarks</a> |                  |       |               |                  | <br>20  | <br>4       |

**Title:** Offensive Odors Inside Cabin

**Applies To:** Post 2010 ProStar

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

11/28/2016 - Removed linked warranty information per SIR compliance regulations  
 7/23/2015 - Fixed links  
 5/23/2014 - Updated "Warranty Information" section to explain coding for failure dates.

## DESCRIPTION

- Driver complaint of offensive odors in the cab.

## TOOLS REQUIRED

- General hand tools
- 1/4 inch drill bit
- Drill

## PARTS INFORMATION

- Cowl Tray Kit : P/N 2511806C91

## REPAIR PROCEDURE

Click on the following items:

- [Diagnostic Flow Chart](#)
- [Cowl Tray Installation Instructions](#)

## OTHER RESOURCES

Click on the following items:

- [Exhaust Leak Troubleshooting for 2010 Emission](#)
- [PDOG Clamp](#)
- [Cowl Tray to Cab Seal Installation Procedure](#)
- [Exhaust Manifold Ring Seal Removal / Installation](#)

- [Exhaust Manifold Gasket Removal and Installation Procedure](#)

|  | Hide Details                                  | Feedback Information |
|-----------------------------------------------------------------------------------|-----------------------------------------------|----------------------|
|                                                                                   | Viewed: 3355<br>Helpful: 20<br>Not Helpful: 4 |                      |
|                                                                                   | No Feedback Found                             |                      |

Copyright © 2016 Navistar, Inc.