

Technical Service Bulletin



20 Corrosion on exhaust tail pipes

20 16 61 2042920/1 March 1, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2007 - 2016	All	Not applicable

Condition

There is corrosion or excessive dirt on the exhaust tailpipes.

Technical Background

If road salt or other substances stick to the exhaust tailpipes for a long time, the surface can get damaged, dirty, and/or rusty.

Production Solution

Not applicable.

Service

- Inform the customer that the exhaust tailpipes must be cleaned regularly.
- Explain to the customer that this damage is due to outside influence and is not covered by any Audi warranty.
- The exhaust tailpipes can be cleaned with care products designed for cleaning stainless steel or with industrial contamination remover (part number ABS 600 000 10).



Note:

- Observe the instructions listed on the product.
- Do not use on plastic parts. Staining can occur.

Warranty

This damage is due to outside influence and is not covered by any Audi warranty.

Technical Service Bulletin



Required Parts and Tools

Part Number	Part Description	Quantity
ABS 600 000 10	Industrial contamination remover	1

Additional Information

All parts and service references provided in this TSB (2042920) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.