



Tech Tips

TT 93-17-01

Date: January 13, 2017

2017 eGolf – 12 Volt Battery not Charging Message or a Red “!” in the MFI

The following faults may be listed in AW 51 Electric Drive: P33CE, P33CC, P33CB, P33D0, U0111. The following fault may also be present in AW 19 Gateway: P1B01. There may also be faults in AW 08 HVAC: U046C, B10CE, B10CD.

Inspect the SA2 fuse for correct torque. If the SA2 fuse is not torqued correctly, the JX1 will not operate as designed and therefore will not recharge the 12 volt battery.

