



TECHNICAL SERVICE BULLETIN

TSB#: 16-013

Job Code: 9801295

Flate Rate:

Inspect ONLY .2 hr

Inspect and Rpl .4 hr

Date of Publication: April 2016

**NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication.
PARTS KIT IS NOT REQUIRED FOR THIS REPAIR.**

ACTION REQUIRED:

Inspect the battery disconnect switch to confirm it is working properly.
Correct wiring to battery disconnect switch when required.

Affected Units

2016 Eagle Fifth Wheels

355MBQS	G1WA0138-0249
291RSTS	G1WB0081-0113
325BHQS	G1WC0110-0183
321RSTS	G1WD016-0204
323LKTS	G1WE0100-0157
345BHQS	G1WF0109-0151
293RKDS	G1WG0094-0151
339FLQS	G1WH0109-0178
360QB0K	G1WJ0052-0122
317RL0K	G1WK0052-0187

TOOLS

11/16 Socket and ratchet **OR** 11/16 wrench

INSPECTION



Open the forward storage compartment where the battery disconnect switch is located.

Turn on a light in the storage compartment.

Turn the battery disconnect switch **OFF**.



If the light **goes out**, the wiring at the disconnect switch is **OK**. **No repair is necessary.**

If the light **stays ON**, proceed to correct the wiring of the switch.



- Fig 1:** Remove nuts from the terminals of the battery disconnect switch and wire for the Power Converter and wire for the 12V Fuse Panel.
- Fig 2:** Reverse the Power Converter wire and the 12V Fuse Panel wire on the battery disconnect switch - tighten with nuts.

(Refer to the schematics on Page 2)





903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-5861 • Fax (574) 825-7354

April 2016

Technical Service Bulletin Notification TSB #16-013

Dear Valued Jayco RV Dealer:

Jayco has determined that certain Model Year 2016 Eagle Fifth Wheels require inspection of the battery disconnect switch to ensure it is working properly. If not, the power converter wire and the 12V fuse panel wire on the switch are reversed and must be corrected.

Our records indicate the following unit is currently part of your inventory and requires the bulletin repair prior to being sold:

Serial number

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (April 2016- April 2017). If you have sold this affected vehicle, please contact the current owner regarding this Service Bulletin and process the Warranty Registration for this customer. All pertinent information regarding this Bulletin is on file under the Service and Parts Tab of Jayco Partners. If you have questions regarding this Service Bulletin, please contact Jayco Customer Service at 800-283-8267.

Sincerely,
Jayco Towable Division



April 2016

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-5861 • Fax (574) 825-7354

Technical Service Bulletin Notification TSB #16-013
Unit Serial Number

Name

Address

City state zip

Dear Valued Jayco RV Owner:

Jayco has determined that certain Model Year 2016 Eagle Fifth Wheels require inspection of the battery disconnect switch to ensure it is working properly. If not, the power converter wire and the 12V fuse panel wire on the switch are reversed and must be corrected.

Our records indicate that your Eagle Fifth Wheel is affected by this service bulletin. Please contact your nearest Jayco dealer to schedule an appointment and present this letter as authorization to have the procedure completed at **no cost** to you.

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (April 2016 – April 2017) If you have sold or traded your vehicle, or for any reason cannot have this service performed, please contact the Jayco Customer Service Department at 800-283-8267.

We apologize for any inconvenience this may cause. However, we are confident that this improvement will offer continued satisfaction with your Jayco fifth wheel.

Sincerely,
Jayco Towable Division