



Countries: BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, MEXICO, ARUBA, NICARAGUA, PERU, PUERTO RICO, Curaçao, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA, SOUTH KOREA, PANAMA
Document ID: IK1200335
Availability: ISIS, Bus ISIS, FleetSIS, IsSIR
Revision: 5
Major System: ENGINES
Created: 11/18/2008
Current Language: English
Last Modified: 10/7/2016
Other Languages: [Français](#), [Español](#),
Author: Marcelo Sahagun
Viewed: 7906

[Less Info](#)
[Hide Details](#)

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Edit Document	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks					 1598	 826

Title: Trouble Code 3338 on 2007 MY Emissions MaxxForce DT, 9 & 10 Engines

Applies To: 2007 MY Emissions MaxxForce DT, 9 & 10 Engines

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/7/2016 - Added SPN/FMI
 04/22/2015 - Author updated for feedback purposes

DESCRIPTION

Active DTC 3338 during a KOER test or an AMS test with a 2007 MY Emissions MaxxForce DT, 9 & 10 Engine.

POSSIBLE DIAGNOSTIC TROUBLE CODES

DTC	SPN	FMI	MODULE	DESCRIPTION
3338	7129	17	Engine	KOER STD - EBP unable to build during test

RESOLUTION

Disregard and clear this fault code.

[Hide Details](#)

Feedback Information

Viewed: 7905
 Helpful: 1598
 Not Helpful: 826

No Feedback Found