

Wiper stops on the windshield without obvious cause at speeds < 6mph.

Topic number	LI82.30-P-064282
Version	1
Design group	82.30 Windshield wipers
Date	06-13-2016
Validity	213
Reason for change	
Reason for block	

Complaint:

Wiper stops on the windshield without obvious cause at speeds < 6mph.

Cause:

A previous software update process using Xentry may not have been performed correctly (applies for all flashing processes, regardless of the control unit).

Remedy:

Update software in front SAM and perform SCN coding.

Note:

During the flashing process, the front wiper system is set to production mode.

When the flashing process is complete, the front wiper system is reset back to driving mode.

If the flashing process is aborted, the front wiper system remains in production mode. Thus only the limp-home capability of the front wiper system is available, which functions only at speeds > 10 km/h

Symptoms
Overall vehicle / Cleaning system / Windscreen wiper / Remains stationary
Overall vehicle / Cleaning system / Windscreen wiper / Malfunction

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			5452E 90	