



Maserati Technical Bulletin

Date: July 6th, 2016
Bulletin No. MAS000881 EPB Bowden Cable
Insulation
Service Campaign 305
Supersedes: NA

MASERATI

MODEL: Ghibli (M157) Quattroporte (M156)

MODEL YEAR: 2016

SUBJECT: Service Campaign 305 – EPB Bowden Cable Insulation

DATE: July 6th, 2016

DESCRIPTION

Some Model Year 2016 Maserati Quattroporte (M156) and Ghibli (M157) vehicles are involved in a Service Campaign to check and if necessary, install a rubber insulation sleeve (Fig.1) over the EPB cables. This sleeve will help to prevent noises and wear of the rubber insulating material on the cables.



Fig.1

To view the vehicles involved in this Campaign, check in ModisCS+ and the attached vin list at the end of this bulletin (Attachment A)

PARTS NEEDED FOR THE REPAIR

For this campaign, you will need to order the rubber sleeve from the Maserati Parts Department. The P/N is: 673006254 (order two for each vehicle). Also needed are 4 generic cable (wire) ties, length 178 mm x width 4.8 mm to fasten the sleeves to the EPB cables.

NOTE: MNA parts is NOT prior releasing parts for this campaign. Please use the PHD system with a valid vin for this campaign for parts release.

OPERATING PROCEDURE

1. Check if the vehicle is involved in this campaign and the campaign hasn't been previously performed.

2. Drive the vehicle onto a lift and check if the rubber insulation sleeve is installed on both sides of the vehicle. (Fig.2)




Fig.2

- If the sleeves are present, install the cable (wire) ties to the sleeve as shown in Fig.2.
- If one or both rubber sleeves are missing, install them using 2 cable (wire) ties on each sleeve as shown in Fig.2.

NOTE: When installing the sleeves, make sure they extend through the guide bracket (red arrow, Fig.2) before securing them with the cable ties.

- Trim the excess material off of the ends of the cable ties when secure.

Warranty Information

• Campaign Number	305
• Warranty Code	23
• Defect Code	063
• Component Code	4.30.102
• Operation Code (EPB Rubber protection installation)	4.30.102.A (0.25h)
• Component Part Number	673006254 (two for each vehicle)

Nicola Rosciano
Manager Technical Support
Maserati North America, Inc.

Luis Sanchez
Technical Director
Maserati North America, Inc.

Attachment “A”

Vehicle	Complete VIN	VIN
Ghibli S Q4 MY16	ZAM57RTAXG1185264	185264
Quattroporte S Q4 MY16	ZAM56RRA2G1185964	185964
Quattroporte S Q4 MY16	ZAM56RRA8G1185967	185967
Ghibli 350 MY16	ZAM57XSA5G1184352	184352
Quattroporte S Q4 MY16	ZAM56RRA9G1185878	185878
Quattroporte S Q4 MY16	ZAM56RRA3G1185956	185956
Ghibli S Q4 MY16	ZAM57RTA8G1184940	184940
Quattroporte S Q4 MY16	ZAM56RRA3G1186024	186024
Ghibli S Q4 MY16	ZAM57RTAXG1184941	184941
Ghibli S Q4 MY16	ZAM57RTA4G1185423	185423
Ghibli S Q4 MY16	ZAM57RTA1G1185234	185234
Quattroporte S Q4 MY16	ZAM56RRAXG1185940	185940
Ghibli S Q4 MY16	ZAM57RTA6G1185326	185326
Ghibli S Q4 MY16	ZAM57RTA4G1185390	185390
Ghibli S Q4 MY16	ZAM57RTA0G1185225	185225
Ghibli S MY16	ZAM57RSAXG1185380	185380
Ghibli S Q4 MY16	ZAM57RTA2G1185355	185355
Quattroporte S MY16	ZAM56RPA0G1185948	185948
Quattroporte S Q4 MY16	ZAM56RRA7G1184308	184308