

September 26, 2016



Customer Name
Address
City, State Zip

Subject: Field Repair 816-3: Seat Belt Too Long

Our records indicate that your vehicle(s) (listed on the back of this page) has been identified as having a seat belt that is too long and may not fully retract into the housing when not in use. The seat belt may fall into the door opening and be damaged.

<i>The problem is...</i>	Seat belt is too long
<i>Correction...</i>	Replace affected seat belts
<i>What you must do ...</i>	Contact your dealer to schedule an appointment

Please contact a Peterbilt dealership to schedule an appointment for this work. If you've already had this work performed, please disregard this letter. You can find the nearest Peterbilt dealer at Dealer Locator on the website www.Peterbilt.com.

When contacting your selected Peterbilt dealer, refer to campaign number **816-3** and the VIN listed on the reverse side of this letter. The upgrade will take approximately **1.0 hours labor** and there will be no charge to you if completed within Standard Warranty (excludes Extended Warranty) or for upgrades completed by **10/01/2017**, whichever is greater.

We apologize for this inconvenience but ask for your cooperation to ensure continued satisfaction with your Peterbilt products.

Thank you,

A handwritten signature in black ink that reads "Douglas H. Gunter".

Doug Gunter
Director of Warranty
Peterbilt Motors Company