

Daimler Trucks North America LLC
March 2016 Section 579.5 External Communication Report

Index

SF514 Western Star ABS Wiring - Export Only
SF522 Western Star 5700 HVAC Fresh Air Inlets
SF525 Western Star 5700 Webasto Air Top 2000 Auxiliary Heaters
ICI16-003 SF514 Revised Bulletin
ICI16-006 FL676 Second Revised Bulletin
16-007 Canadian Warranty Parts Return Address Change
16-008 New Detroit Bearing Failure Analysis Standard Diagnostic Time
16-009R_OWL Enhancements
16-010 Warranty Recognition Program Suspension
16-011 New Detroit Camshaft Housing Seal Standard Repair Time

18SP731 GHG17 Heavy Duty Flywheel Special Notice
0303-16 Hydrocarbon Doser Coolant Lines
0302-16 Contaminated Fluids
0301-16 SPN 625 (CPC) (EPA07) and SPN 625 (CPC) (EPA10 GHG14)
0307-16 SPN 723 (MCM) March
0304-16 SPN 2791 (MCM) (GHG14) and SPN 2791 (MCM) (GHG17)
0306-16 TCM SPN 520970 FMI 7
0305-16 TCM SPN 520999 FMI 7 March
0308-16 TCM Programming Instruction
16TS5 Release of the DD Platform Bearing Failure Guide
16TS6 Variable-Speed Fan Operation on Cascadia Vehicles
16TS7 Reman Diesel Particulate Filter Serial Number
16TS8 DD13 Cylinder Head and Cylinder Head Gasket Change
16TS9 DD Platform High Pressure Fuel Lines
16_TL-2 DD Platform Aftertreatment NOx Sensor Socket W470589060900
16TL3 Pocket iQ™ ABS Product Family Kit is Available at PDC
16TL4 DOC Face Cleaning Tool P N W470589239100
16TL5 DD Platform Aftertreatment Soot Sensor Socket DSN0ATZ16001
16-008 New Detroit Bearing Failure Analysis Standard Diagnostic Time

FL676 - Haldex Life Seal Brake Chambers

Minotour Label FSC SF521 Replacing entrance door manual operation label
SF521 TBB Entrance Door Labels