

PRODUCT UPDATE

UTILITY TRAILER MANUFACTURING CO.



PU-08-005

Issue date: March 17, 2016

Product Update Hendrickson Height Control Valve (HCV) Kits

Please read the attached product update from Hendrickson. If you have any questions regarding the information indicated, please contact your Hendrickson service representative at 330.489.0045

Any other questions regarding this product update should be directed to Utility's Field Service Department at 800-423-6591.

Field Service Department
UTILITY TRAILER MANUFACTURING COMPANY

Utility hasn't independently evaluated the information contained in the attached Height Control Valve (HVC) Kits Update from Hendrickson; it is making the product update available as a convenience and for information purposes. You are encouraged to contact Hendrickson at (330-489-0045) if you have any questions concerning the content of the document, or how these issues affect trailers you are servicing.



February 23, 2016

Attention:

**Engineering Managers
Purchasing Managers
Production Managers
Quality Managers
Service Managers
Parts Managers**

(Please copy to other concerned departments)

Please see attached document!

Product Update:


Height Control Valve (HCV) Kits

PRODUCT UPDATE Height Control Valve (HCV) Kits


LIT NO: P56035

DATE: February 2016

Hendrickson Trailer Commercial Vehicle Systems announces a change to height control valve (HCV) kits used with AAL suspensions featuring the Large-Diameter Axle (LDA™). The lower mounting bracket has been modified to provide an optimized solution for both drum brake- and air disc brake-equipped suspensions. As shown below, the mounting hole locations remain the same, and therefore the attachment method is unchanged. The shape of the bracket has simply been revised.



**Current Lower
Mounting Bracket
(VS-31075)**



**New Lower
Mounting Bracket
(VS-37016-1)**

The following HCV kits will include the new lower mounting bracket, effective with orders shipped on or after February 29th, 2016. The new bracket, VS-37016-1, will replace the current bracket, VS-31075, in the aftermarket.

HCV Kit Number	Description	Suspension Models
AKH0306-3	Standard HCV Kit	INTRAAX® AAL 23K/25K/30K VANTRAAX® HKAL/HKARL 46K INTRAAX-SP AAZL 23K/46K
AKH0306B-3	Standard HCV Kit Less PPV	
AKHD0306-3	Integral Dump HCV Kit	
AKHD0306F-3	Integral Dump HCV Kit Less Brass Fittings	
AKH0309	HCV Hardware Kit	
AKH0309-1	HCV Hardware Kit Less Brass Fittings & Link Assembly	

Hendrickson is committed to providing world-class, quality products and exceptional customer service. For additional assistance, please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247).

Call Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601