



Ferrari North America

Technical Information

Date: June 2017
Bulletin #: 2424
Campaign #:
Supersedes:
Section: 10

Subject: Updated contents with reference to TI 2423

Please find enclosed the tables amended by the most recent Technical Documentation update (ModisCS and Pen-Drive) released on April 12, 2017.

- IMPORTANT -

Please read the contents of these updates carefully to help ensure that all vehicle repair procedures are performed correctly to avoid wasted time and help ensure rapid problem resolution.

Please note that any repair / replacement work not compliant with the procedures described in the paragraphs listed below may result in rejection of the warranty claim and, as a result, the relative costs incurred will not be reimbursed.

- GTC4Lusso T:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR VEHICLES SUBJECT TO TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- GTC4Lusso:

- First release of Workshop Manual, **Europe RHD version.**

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.



Ferrari North America

E5.13 _ Infotainment system

- Added chapter REPLACING GPS NAVIGATOR SD CARD.

- LaFerrari Aperta:

- First release of Workshop Manual, **USA version**.

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- LaFerrari:

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- FF:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

D4.08 _ Vehicle Lift system (optional)

- Added chapter INSTALLING LIFT SYSTEM PUMP REPLACEMENT KIT
- Updated chapter FILLING AND BLEEDING LIFT SYSTEM
- Updated chapter CHECKING LIFT SYSTEM OIL LEVEL.

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSSHIELD.



Ferrari North America

- California T:

A1.02 _ Fluids and lubricants table

- FLUIDS AND LUBRICANTS TABLE updated.

B2.01 _ Complete engine removal

- Updated procedure for removing complete engine.

B2.02 _ Complete engine reassembly

- Updated procedure for refitting complete engine.

B2.03 _ Engine overhaul - Disassembly

- Updated procedure for removing engine timing cover.

B2.05 _ Engine overhaul - Reassembly

- Updated procedure for refitting engine timing cover.

C4.04 _ Flywheel

- Updated procedure for removing and refitting flywheel.

D2.01 _ Complete wheels

- Added procedure for applying Molykote to wheels (applicable only for track use).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- 488GTB:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.



Ferrari North America

- 488Spider

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- F12berlinetta:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- F12tdf:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- California:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.



Ferrari North America

- 458 Speciale A:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- 458 Speciale:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- 458 Italia:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

- California:

D2.01 _ Complete wheels

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.



Ferrari North America

D2.01 _ Complete wheels

- 458 Italia:

- Added chapter APPLYING MOLYKOTE TO WHEELS (APPLICABLE ONLY FOR TRACK USE).

E3.06 _ Windscreen

- Updated chapter REPLACING WINDSHIELD.

Spare Parts Catalog

This update includes all changes to the Spare Parts Catalog concerning the models included in the Technical Documentation, up to **March 13, 2017**.

Some of the more significant updates are indicated below:

- GTC4Lusso T:

Tab.2

- Updated fastener

Tab.7

- Updated spark plug

Tab.8

- Updated table

Tab.9

- Updated fuel pump

Tab.12

- Added air pressure sensor mounting bracket

Tab.16

- Added fasteners



Ferrari North America

Tab.17

- Updated air filter

Tab.23

- Updated oil filter cartridge

Tab.27

- Added complete bush travel limiter bracket

Tab.28

- Updated long heat shield

Tab.37

- Updated fastener

Tab.38

- Updated table

Tab.40

- Updated front shock absorber

Tab.42

- Updated rear shock absorber

Tab.47

- Updated belt

Tab.102

- Updated table

Tab.105

- Added components

Tab.107

- Updated RH dashboard insulation



Ferrari North America

Tab.108

- Updated front removable mat kit

Tab.110

- Updated table

Tab.113

- Added shim

Tab.115

- Added fastener

Tab.116

- Added fastener

Tab.118

- Added fasteners

Tab.120

- Updated table

Tab.121

- Updated table

Tab.122

- Updated table

Tab.123

- Updated table

Tab.124

- Updated table

Tab.127

- Added kin for passive start system



Ferrari North America

Tab.131

- Updated table

Tab.132

- Updated fasteners

Tab.134

- Updated table

Tab.135

- Updated table

Tab.136

- Added components

Tab.137

- Added components

- LaFerrari Aperta:

Included market-specific components

Tab.116

- Updated table

Tab.118

- Updated front dashboard grill

Tab.128

- Added wiring harness mounting bracket

Tab.130

- Updated table



Ferrari North America

Tab.135

- ADDED TABLE

- GTC4Lusso:

Included market-specific components

Tab.20

- Updated LH lower bracket

Tab.26

- Updated clamp

Tab.32

- Updated table

Tab.36

- Updated rear shock absorber

Tab.46

- Updated table

Tab.105

- Added fender fastener brackets on RH/LH front trellis

Tab.106

- Updated shield for front section of RH/LH front wheelhouse.

Tab.107

- Updated table

Tab.108

- Updated removable mat kits



Ferrari North America

Tab.110

- Updated table

Tab.111

- Updated fastener

Tab.113

- Added shim

Tab.115

- Added fastener

Tab.116

- Added fastener

Tab.118

- Added fastener

Tab.120

- Updated table

Tab.121

- Updated table

Tab.122

- Updated table

Tab.123

- Updated table

Tab.124

- Updated table

Tab.125

- Updated table



Ferrari North America

Tab.127

- Added kin for passive start system

Tab.131

- Updated table

Tab.134

- Updated table

Tab.135

- Updated table

Tab.136

- Updated table

Tab.137

- Added components

Tab.138

- Added airbag warning label

- F12tdf:

Tab.12

- Updated table

Tab.17

- Updated oil pipe from tank to disconnecter

Tab.18

- Updated complete oil pump

Tab.36

- Added fastener



Ferrari North America

Tab.37

- Updated self-adhesive wheel balancing weight

Tab.46

- Added airbag information pamphlet

Tab.109

- Updated screw cover cap

Tab.115

- Updated door handle shim

Tab.117

- Updated LH outer fin

Tab.123

- Updated firewall bracket

Tab.125

- Updated F1 gearbox controls

Tab.127

- Updated complete RH/LH sill outer trim

Tab.137

- Added airbag warning label

- 488 Spider:

Tab.8

- Added pressure reducer gasket

Tab.12

- Updated table



Ferrari North America

Tab.51

- Updated table

Tab.107

- Updated table

Tab.112

- Updated spacer

Tab.120

- Updated table

Tab.121

- Updated table

Tab.122

- Updated table

Tab.123

- Updated table

Tab.124

- Updated table

Tab.126

- Added glove compartment reinforcement bracket

Tab.128

- Added components

Tab.137

- Updated USB-telemetry node cable



Ferrari North America

Tab.140

- Added airbag warning label

- 488 GTB:**Tab.8**

- Added pressure reducer gasket

Tab.12

- Updated table

Tab.37

- Updated lined bracket

Tab.51

- Updated table

Tab.107

- Updated table

Tab.109

- Updated fasteners

Tab.119

- Updated table

Tab.120

- Updated table

Tab.121

- Updated table



Ferrari North America

Tab.122

- Updated table

Tab.123

- Updated table

Tab.125

- Added glove compartment reinforcement bracket

Tab.127

- Added components

Tab.129

- Updated fasteners

Tab.136

- Updated USB-telemetry node cable

Tab.139

- Added airbag warning label

Tab.130

- 458 Italia:

- Updated rear cable

Tab.7

- California T:

- Updated fastener



Ferrari North America

Tab.10

- Updated fuel pump

Tab.11

- Added pressure reducer gasket

Tab.21

- Updated heat exchanger

Tab.104

- Updated fastener

Tab.107

- Updated fastener

Tab.121

- Updated digital front parking camera

Tab.129

- Updated glove compartment handle

Tab.132

- Updated fastener

- LaFerrari:

Tab.128

- Added wiring harness mounting bracket

Tab.130

- Updated lift system ECU



Ferrari North America

- F12berlinetta:

Tab.48

- Added airbag information pamphlet

Tab.107

- Updated firewall insulation

Tab.108

- Updated fastener

Tab.109

- Updated table

Tab.115

- Updated door handle shim

Tab.125

- Updated firewall bracket

Tab.140

- Added airbag warning label

- California:

Tab.30

- Updated protective foam

Tab.134

- Updated RH seat complete with guide rails

Tab.154

- Updated navigator head unit



Ferrari North America

Tab.46

- 599 GTB Fiorano:

- Updated table

S.T. Schedule

The S.T. Schedule has been updated in consideration of the changes to the Spare Parts Catalog.

Thank you for your co-operation.