



210 Inverness Center Drive
Birmingham, AL 35242

Telephone: 205-991-7733
Facsimile: 205-991-9993
www.altec.com

July 5, 2017

Dear Altec Owner,

Altec Industries, Inc. has developed a product improvement which relates to certain AA/AN50, AA/AN55, AA/AN60, AA/AN67, AN46-OC, AN50-OC, AN55-OC, AM50, AM55, AM50E, AM55E, AM57, AM60, AM60E units built between June 2016 and December 2016.

Refer to SIL 659 for items covered under the warranty policy.

In order to determine if your unit is affected by SIL 659, compare the serial number of your unit with the list of affected units as described on the SIL. The product improvement can be performed by the customer or you may contact Altec at 1-877-GO-ALTEC (1-877-462-5832) for further assistance.

At any time, you may contact Altec at 1-877 GO ALTEC (1-877-462-5832) with your unit's serial number to determine if there are any other outstanding notices.

If you have sold or retired the unit please call Altec at 1-877-GO-ALTEC (1-877-462-5832) so the records may be changed.

We regret this inconvenience; however we are taking this action in the interest of your safety and continued satisfaction with Altec products.

Thank you for your immediate attention on this important matter.



Altec Industries, Inc.
Midwest Division
St. Joseph, MO

SIL 659

Service Information Letter

Date: July 5, 2017

Units Affected: AA/AN50, AA/AN55, AA/AN60, AA/AN67, AN46-OC, AN50-OC, AN55-OC, AM50, AM55, AM50E, AM55E, AM57, AM60, AM60E units built between June 2016 and December 2016 (see attached list).

Note: this does NOT include AA/AN67-E100 and AA/AN67E-E100

Lower Control Valve Station Selector Improvement

Altec is committed to providing our customers reliable products from initial delivery throughout the useful life of the machine.

The affected units were manufactured with a manually actuated lower control station selector valve which must be held to engage lower controls. Altec has determined the manual selector valve can fail to shift or operate in some situations. As a result, a change has been made to replace the manual valve with an electrohydraulic valve. In addition, the secondary stowage switch is being relocated closer to the station selector so that one user can operate both functions.

Altec requires verification that the electrohydraulic valve has been installed no later than the next maintenance interval after the receipt of this SIL. Inspect the unit to verify that the lower control station selector valve has not been replaced with the electrohydraulic valve (refer to Figure 1). If the lower control station selector valve has been replaced with the electrohydraulic valve, no further action needs to be done and the SIL is complete. If the original manual valve is still on the lower control valve (refer to Figure 2), it must be replaced.




Figure 1 — Electrohydraulic Valve



Figure 2 — Original Manual Valve

Altec has created a kit for this improvement. Call 1-877-GO ALTEC (1-877-462-5832) to order the correct kit for the unit using the chart below.

Unit	Kit Number
AA50-55-60-67, AN50-55-60-67, AN46-OC, 50-OC, 55-OC	990364398
AM50-55-57-60 and E	990364402

This update is covered under the Altec Warranty Policy and can be performed by Altec or the customer’s warranty provider. Altec will allow up to \$360 for the labor to perform this update. A warranty claim must be submitted for the cost of the parts and the labor. Call 1-877-GO ALTEC (1-877-462-5832) to schedule the work to be done by an Altec service technician. Customers are responsible for the travel costs of an Altec Mobile Service technician if the technician performs the inspection or update at the owner’s location.