

Date	Expiration	Release	Page
08.2016	08.2018	0	1(2)

MUX UPDATE - DRIVER'S WINDOW & ENTRANCE

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, update the MUX software to the latest version.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 coaches Model Year : 2017	2PCG3349XHC736092, 2PCG33495HC736114, 2PCG33490HC736117
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

No material is required

PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

With Laptop and VPG software, Connect to the vehicle and update the MUX software to the latest version.

PARTS / WASTE DISPOSAL

Discard waste generated by bulletin activities according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)
--

ESTIMATED TIME

Date	Expiration	Release	Page
08.2016	08.2018	0	2(2)

The time required to perform this special bulletin is approximately 30 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	06.00
Defect Code	49
Syst. Cond	B
Causal Part	7770029

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>

or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type
"ADD" in the subject to receive our warranty bulletins by e-mail.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.