

Field campaign

Topic	Mulsanne side view camera control module (SC12/15)
Market area	Bentley: worldwide (2WBE)
Brand	Bentley
Transaction No.	2030874/4
Campaign number	E775
Note	E775
Type	
US code	

Vehicle data

Mulsanne

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3Y2*	2012	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	BB7	ZH	5	C	C	016219	016219		
SCB	BB7	ZH	1	C	C	016220	016220		
SCB	BB7	ZH	5	C	C	016222	016222		
SCB	BA6	3Y	1	C	C	016224	016224		
SCB	BA6	3Y	9	C	C	016228	016228		
SCB	BA6	3Y	7	C	C	016230	016230		
SCB	BA6	3Y	4	C	C	016234	016234		
SCB	BB7	ZH	3	C	C	016235	016235		
SCB	BB7	ZH	5	C	C	016236	016236		
SCB	BB7	ZH	7	C	C	016240	016240		
SCB	BA6	3Y	7	C	C	016244	016244		
SCB	BB7	ZH	6	C	C	016245	016245		
SCB	BA6	3Y	6	C	C	016249	016249		
SCB	BA6	3Y	4	C	C	016251	016251		
SCB	BA6	3Y	3	C	C	016256	016256		
SCB	BB7	ZH	2	C	C	016260	016260		
SCB	BA6	3Y	0	C	C	016263	016263		
SCB	BB7	ZH	7	C	C	016271	016271		
SCB	BB7	ZH	9	C	C	016272	016272		
SCB	BB7	ZH	6	C	C	016276	016276		
SCB	BB7	ZH	1	C	C	016279	016279		
SCB	BA6	3Y	6	C	C	016283	016283		
SCB	BB7	ZH	2	C	C	016288	016288		
SCB	BB7	ZH	4	C	C	016289	016289		
SCB	BB7	ZH	3	C	C	016297	016297		
SCB	BA6	3Y	2	C	C	016300	016300		
SCB	BA6	3Y	2	D	C	016301	016301		
SCB	BA6	3Y	6	D	C	016303	016303		
SCB	BB7	ZH	4	C	C	016308	016308		
SCB	BA6	3Y	7	C	C	016311	016311		
SCB	BA6	3Y	2	C	C	016314	016314		
SCB	BB7	ZH	7	C	C	016321	016321		
SCB	BA6	3Y	3	C	C	016323	016323		
SCB	BA6	3Y	2	C	C	016331	016331		
SCB	BA6	3Y	6	C	C	016333	016333		
SCB	BB7	ZH	7	C	C	016335	016335		
SCB	BA6	3Y	5	C	C	016341	016341		

SCB	BB7	ZH	4	C	C	016342	016342		
SCB	BB7	ZH	8	C	C	016344	016344		
SCB	BA6	3Y	2	C	C	016345	016345		
SCB	BB7	ZH	3	C	C	016347	016347		
SCB	BA6	3Y	X	C	C	016349	016349		
SCB	BA6	3Y	7	C	C	016356	016356		
SCB	BA6	3Y	0	C	C	016358	016358		
SCB	BA6	3Y	2	C	C	016362	016362		
SCB	BB7	ZH	5	C	C	016365	016365		
SCB	BA6	3Y	5	C	C	016369	016369		
SCB	BB7	ZH	8	C	C	016375	016375		
SCB	BA6	3Y	2	C	C	016376	016376		
SCB	BA6	3Y	6	C	C	016378	016378		
SCB	BB7	ZH	3	C	C	016381	016381		
SCB	BA6	3Y	1	C	C	016384	016384		
SCB	BB7	ZH	0	C	C	016385	016385		
SCB	BA6	3Y	5	C	C	016386	016386		
SCB	BA6	3Y	7	C	C	016387	016387		
SCB	BA6	3Y	0	C	C	016389	016389		
SCB	BA6	3Y	9	C	C	016391	016391		
SCB	BA6	3Y	4	C	C	016394	016394		
SCB	BA6	3Y	X	C	C	016397	016397		
SCB	BB7	ZH	0	C	C	016399	016399		
SCB	BB7	ZH	5	C	C	016401	016401		
SCB	BA6	3Y	5	C	C	016405	016405		
SCB	BA6	3Y	9	C	C	016407	016407		
SCB	BA6	3Y	9	C	C	016410	016410		
SCB	BA6	3Y	8	C	C	016415	016415		
SCB	BA6	3Y	1	C	C	016417	016417		
SCB	BA6	3Y	5	C	C	016419	016419		
SCB	BA6	3Y	5	C	C	016422	016422		
SCB	BA6	3Y	9	C	C	016424	016424		
SCB	BA6	3Y	2	C	C	016426	016426		
SCB	BA6	3Y	4	C	C	016427	016427		
SCB	BA6	3Y	8	C	C	016432	016432		
SCB	BA6	3Y	1	C	C	016434	016434		
SCB	BB7	ZH	2	C	C	016436	016436		
SCB	BA6	3Y	0	C	C	016439	016439		
SCB	BA6	3Y	0	C	C	016442	016442		
SCB	BA6	3Y	8	C	C	016446	016446		
SCB	BA6	3Y	X	C	C	016447	016447		
SCB	BC6	3Y	9	C	C	016451	016451		
SCB	BA6	3Y	2	C	C	016457	016457		
SCB	BA6	3Y	2	C	C	016460	016460		
SCB	BB7	ZH	7	C	C	016464	016464		
SCB	BA6	3Y	1	C	C	016465	016465		
SCB	BA6	3Y	9	C	C	016469	016469		
SCB	BA6	3Y	5	C	C	016470	016470		
SCB	BA6	3Y	8	C	C	016477	016477		
SCB	BA6	3Y	X	C	C	016481	016481		
SCB	BA6	3Y	5	C	C	016484	016484		
SCB	BB7	ZH	8	C	C	016487	016487		
SCB	BA6	3Y	2	C	C	016488	016488		
SCB	BA6	3Y	0	C	C	016490	016490		
SCB	BA6	3Y	4	C	C	016492	016492		
SCB	BA6	3Y	X	C	C	016495	016495		
SCB	BB7	ZH	9	C	C	016496	016496		
SCB	BA6	3Y	5	C	C	016498	016498		
SCB	BA6	3Y	3	C	C	016502	016502		

SCB	BA6	3Y	0	C	C	016506	016506		
SCB	BA6	3Y	4	C	C	016508	016508		
SCB	BA6	3Y	6	C	C	016509	016509		
SCB	BA6	3Y	6	C	C	016512	016512		
SCB	BB7	ZH	7	C	C	016514	016514		
SCB	BA6	3Y	9	C	C	016519	016519		
SCB	BA6	3Y	5	C	C	016520	016520		
SCB	BA6	3Y	6	C	C	016526	016526		
SCB	BA6	3Y	8	C	C	016527	016527		
SCB	BA6	3Y	8	C	C	016530	016530		
SCB	BA6	3Y	0	C	C	016537	016537		
SCB	BA6	3Y	0	C	C	016540	016540		
SCB	BA6	3Y	3	C	C	016547	016547		
SCB	BA6	3Y	4	C	C	016542	016542		
SCB	BA6	3Y	6	C	C	016543	016543		
SCB	BA6	3Y	5	C	C	016548	016548		
SCB	BA6	3Y	X	C	C	016559	016559		
SCB	BA6	3Y	3	C	C	016564	016564		
SCB	BA6	3Y	5	C	C	016565	016565		
SCB	BA6	3Y	4	C	C	016573	016573		
SCB	BA6	3Y	8	C	C	016575	016575		
SCB	BC6	3Y	4	C	C	016583	016583		
SCB	BB7	ZH	3	C	C	016588	016588		
SCB	BA6	3Y	4	C	C	016590	016590		
SCB	BA6	3Y	0	C	C	016604	016604		
SCB	BA6	3Y	2	C	C	016605	016605		
SCB	BA6	3Y	X	C	C	016612	016612		
SCB	BA6	3Y	1	C	C	016613	016613		
SCB	BA6	3Y	3	C	C	016614	016614		
SCB	BA6	3Y	7	C	C	016616	016616		
SCB	BA6	3Y	2	C	C	016619	016619		
SCB	BA6	3Y	1	C	C	016627	016627		
SCB	BA6	3Y	4	C	C	016671	016671		
SCB	BA6	3Y	3	C	C	016676	016676		
SCB	BA6	3Y	5	C	C	016677	016677		
SCB	BB7	ZH	4	C	C	016678	016678		
SCB	BB7	ZH	6	C	C	016679	016679		
SCB	BA6	3Y	5	C	C	016680	016680		
SCB	BA6	3Y	7	C	C	016681	016681		
SCB	BA6	3Y	0	C	C	016683	016683		
SCB	BA6	3Y	2	C	C	016684	016684		
SCB	BA6	3Y	1	C	C	016689	016689		
SCB	BA6	3Y	3	C	C	016693	016693		
SCB	BB7	ZH	4	C	C	016695	016695		
SCB	BB7	ZH	8	C	C	016697	016697		
SCB	BA6	3Y	7	C	C	016700	016700		
SCB	BA6	3Y	0	C	C	016702	016702		
SCB	BA6	3Y	6	C	C	016705	016705		
SCB	BB7	ZH	9	C	C	016708	016708		
SCB	BA6	3Y	3	C	C	016709	016709		
SCB	BA6	3Y	X	C	C	016710	016710		
SCB	BB7	ZH	9	C	C	016711	016711		
SCB	BB7	ZH	0	C	C	016712	016712		
SCB	BB7	ZH	2	C	C	016713	016713		
SCB	BA6	3Y	9	C	C	016715	016715		
SCB	BB7	ZH	1	C	C	016718	016718		
SCB	BB7	ZH	3	C	C	016719	016719		
SCB	BA6	3Y	8	C	C	016723	016723		
SCB	BA6	3Y	X	C	C	016724	016724		

SCB	BB7	ZH	9	C	C	016725	016725		
SCB	BA6	3Y	3	C	C	016726	016726		
SCB	BA6	3Y	5	C	C	016727	016727		
SCB	BA6	3Y	7	C	C	016731	016731		
SCB	BA6	3Y	0	C	C	016733	016733		
SCB	BB7	ZH	1	C	C	016735	016735		
SCB	BA6	3Y	8	C	C	016737	016737		
SCB	BA6	3Y	X	C	C	016738	016738		
SCB	BA6	3Y	1	C	C	016739	016739		
SCB	BA6	3Y	X	C	C	016741	016741		
SCB	BB7	ZH	0	C	C	016743	016743		
SCB	BB7	ZH	4	C	C	016745	016745		
SCB	BB7	ZH	6	C	C	016746	016746		
SCB	BA6	3Y	0	C	C	016747	016747		
SCB	BA6	3Y	2	C	C	016748	016748		
SCB	BA6	3Y	4	C	C	016749	016749		
SCB	BB7	ZH	3	C	C	016753	016753		
SCB	BB7	ZH	7	C	C	016755	016755		
SCB	BB7	ZH	0	C	C	016757	016757		
SCB	BC6	3Y	2	C	C	016758	016758		
SCB	BA6	3Y	7	C	C	016762	016762		
SCB	BA6	3Y	0	C	C	016764	016764		
SCB	BA6	3Y	8	C	C	016771	016771		
SCB	BA6	3Y	1	C	C	016773	016773		
SCB	BB7	ZH	0	C	C	016774	016774		
SCB	BB7	ZH	4	C	C	016776	016776		
SCB	BA6	3Y	2	C	C	016779	016779		
SCB	BA6	3Y	2	C	C	016782	016782		
SCB	BA6	3Y	4	C	C	016783	016783		
SCB	BA6	3Y	5	C	C	016789	016789		
SCB	BB7	ZH	9	C	C	016790	016790		
SCB	BB7	ZH	2	C	C	016792	016792		
SCB	BB7	ZH	6	C	C	016794	016794		
SCB	BB7	ZH	8	C	C	016795	016795		
SCB	BB7	ZH	X	C	C	016796	016796		
SCB	BB7	ZH	5	C	C	016799	016799		
SCB	BA6	3Y	4	C	C	016802	016802		
SCB	BA6	3Y	6	C	C	016803	016803		
SCB	BA6	3Y	1	C	C	016806	016806		
SCB	BA6	3Y	7	C	C	016809	016809		
SCB	BA6	3Y	9	C	C	016813	016813		
SCB	BB7	ZH	1	C	C	016816	016816		
SCB	BA6	3Y	6	C	C	016820	016820		
SCB	BC6	3Y	7	C	C	016822	016822		
SCB	BA6	3Y	3	C	C	016824	016824		
SCB	BA6	3Y	7	C	C	016826	016826		
SCB	BB7	ZH	8	C	C	016828	016828		
SCB	BB7	ZH	6	C	C	016830	016830		
SCB	BA6	3Y	2	C	C	016832	016832		
SCB	BA6	3Y	6	C	C	016834	016834		
SCB	BA6	3Y	1	C	C	016837	016837		
SCB	BA6	3Y	5	C	C	016839	016839		
SCB	BA6	3Y	3	C	C	016841	016841		
SCB	BA6	3Y	8	C	C	016849	016849		
SCB	BA6	3Y	4	C	C	016850	016850		
SCB	BA6	3Y	6	C	C	016851	016851		
SCB	BA6	3Y	7	C	C	016857	016857		
SCB	BA6	3Y	7	C	C	016860	016860		
SCB	BA6	3Y	9	C	C	016861	016861		

SCB	BA6	3Y	8	C	C	016866	016866		
SCB	BA6	3Y	1	C	C	016868	016868		
SCB	BA6	3Y	4	C	C	016878	016878		
SCB	BA6	3Y	X	C	C	016898	016898		
SCB	BA6	3Y	1	C	C	016949	016949		
SCB	BA6	3Y	6	C	C	017031	017031		
SCB	BA6	3Y	2	C	C	017043	017043		
SCB	BB7	ZH	6	C	C	016181	016181		
SCB	BB7	ZH	8	C	C	016182	016182		
SCB	BB7	ZH	X	C	C	016183	016183		
SCB	BB7	ZH	3	C	C	016185	016185		
SCB	BB7	ZH	0	C	C	016189	016189		
SCB	BB7	ZH	5	C	C	016186	016186		
SCB	BB7	ZH	7	C	C	016187	016187		
SCB	BB7	ZH	9	C	C	016188	016188		
SCB	BB7	ZH	9	C	C	016191	016191		
SCB	BB7	ZH	2	C	C	016193	016193		
SCB	BB7	ZH	4	C	C	016194	016194		
SCB	BB7	ZH	6	C	C	016195	016195		
SCB	BB7	ZH	8	C	C	016196	016196		
SCB	BB7	ZH	X	C	C	016197	016197		
SCB	BB7	ZH	1	C	C	016198	016198		
SCB	BB7	ZH	3	C	C	016199	016199		
SCB	BB7	ZH	1	C	C	016203	016203		
SCB	BA6	3Y	6	C	C	016204	016204		
SCB	BB7	ZH	7	C	C	016206	016206		
SCB	BB7	ZH	9	C	C	016207	016207		
SCB	BB7	ZH	2	C	C	016209	016209		
SCB	BB7	ZH	9	C	C	016210	016210		
SCB	BB7	ZH	0	C	C	016211	016211		
SCB	BA6	3Y	7	C	C	016213	016213		
SCB	BB7	ZH	8	C	C	016215	016215		
SCB	BB7	ZH	X	C	C	016216	016216		
SCB	BB7	ZH	1	C	C	016217	016217		

Documents

Document name
master.xml
sideviewcamera.doc



■

Notes

[Repair instructions](#)

Technical background

In January 2012 a TPI was released which instructed Dealers to remove where fitted the side view camera control module as a potential fault was identified with the original part. The latest specification side view camera control module is now available for all Bentley Mulsanne vehicles which were specified with the side view camera option. If the original module has been previously removed and replaced with the link loom as per previous instruction, a Yellow paint mark will be evident on the diagnostic plug surrounding cover as shown in Figure 1, please remove the loom and fit the replacement side view camera module as detailed within this document.




Figure 1

Should the vehicle still have the original side view camera module fitted or the link loom was installed at the time of production a Yellow paint mark will not be evident, if this is the case please replace the existing module or remove the link loom and replace with the latest specification part as detailed within this document.

NOTE: During this procedure the Workshop Manual is quoted, it is recommended that the procedures referenced are checked by the operative as the process within the workshop manual may have changed since last viewed.

Remedy

From Mid-January 2013 the side view camera will again become a customer option, the latest specification part will be fitted at the time of production.

Customer notification

Where possible please ask the customer to ensure the owners handbook is with the vehicle when they visit the Dealership to have the Campaign applied, this is to allow the addendum to be removed which was previously inserted when the original control module was removed. Please also inform your new and used car sales departments of this Campaign so that the vehicles affected can be repaired immediately.

Warranty

Left Hand Drive

Warranty Type	790 or 710
Labour operation code	90 83 19 01
Damage Service Number	E775
Damage Code	00 66
Criteria ID	01
Time	30 time units

Right Hand Drive

Warranty Type	790 or 710
Labour operation code	90 83 19 02
Damage Service Number	E775
Damage Code	00 66
Criteria ID	01
Time	50 time units

Parts

Part Number	Description	Quantity
3Y0 907 589A	Side view camera control module	1

Parts supply

The required replacement part should be ordered from Bentley Motors Limited Crewe or through your regional Bentley parts distribution centre.

Parts despatch control

Not applicable

Repair instructions

Notes

Technical background

In January 2012 a TPI was released which instructed Dealers to remove where fitted the side view camera control module as a potential fault was identified with the original part. The latest specification side view camera control module is now available for all Bentley Mulsanne vehicles which were specified with the side view camera option. If the original module has been previously removed and replaced with the link loom as per previous instruction, a Yellow paint mark will be evident on the diagnostic plug surrounding cover as shown in Figure 1, please remove the loom and fit the replacement side view camera module as detailed within this document.




Figure 1

Should the vehicle still have the original side view camera module fitted or the link loom was installed at the time of production a Yellow paint mark will not be evident, if this is the case please replace the existing module or remove the link loom and replace with the latest specification part as detailed within this document.

NOTE: During this procedure the Workshop Manual is quoted, it is recommended that the procedures referenced are checked by the operative as the process within the workshop manual may have changed since last viewed.

Check

If the vehicle is not already listed as repaired in "Repair history" (in Elsa pro), check for the Campaign completion identification mark which is a White paint mark located above the diagnostic plug cover (Figure 2) the White mark confirms the latest specification part has been fitted, should neither be evident carry out the required work in accordance with instructions.

Parts

Part Number	Description	Quantity
3Y0 907 589A	Side view camera control module	1

Work

1. Remove the side view control module temporary link loom or remove the existing side view camera control module - Refer to Workshop Manual Rep.Gr 94
2. Fit the latest specification control module - Refer to Workshop Manual Rep.Gr 94
3. Should the original side view camera control module have been previously removed and replaced with the link loom 3Y0 998 381 there should be a Yellow completion paint mark on the diagnostic plug surrounding cover (Figure 1), please carefully remove this and replace with a White paint completion mark as shown in Figure 2. If the original control module has been replaced for the latest specification part or the factory fitted loom has been replaced with the latest specification part, a White paint completion mark should also be added (Figure 2)
4. Remove and discard the addendum from the owners handbook which was inserted after the original control module was removed the part numbers for the addendums were as follows:
TSD B05900 - Handbook Addendum - English
TSD B09109 - Handbook Addendum - Multilingual

Identification

White paint mark on the diagnostic plug surrounding cover confirms the latest specification part has been fitted.



Figure 2

▫ **Repair instructions** ▫ **Notes**