

HUSQVARNA TECHNICAL BULLETIN TB1710

July 25, 2017

SUBJECT: SEAT REPAIR SOLUTION FOR 701 MODELS

INITIAL INFORMATION:

In the course of the seat manufacturing process an error may have occurred when attaching the decals. This may result in the discoloration or the peeling and delamination of one or both of the decals.

Husqvarna Motorcycles has developed a repair kit which can be used to change the decal on the seat of 701 ENDURO and 701 SUPERMOTO models if it is discolored or peeling away.

If you have a customer that has a seat with a damaged decal please order (QTY. 1 per seat) a new decal set using **p.n. 270.07.097.000**. We will not accept warranty claims requesting credit for seat replacements.

Please follow the instructions included with the decal repair kit to achieve a long-lasting, good quality result.


After the seat decal repair is complete, prepare a warranty claim using the claim input information below and attach a before and after photo of the seat.

Only warranty claims containing the data specified below will be accepted:

Labor time: T3900207970 Other working time - 20 minutes

Failure code: 300 - Loose glued joint

Spare parts: 27007097000 - Decal set seat 701



COPYRIGHT NOTICE

The user acknowledges that all components of this technical information are Husqvarna's and/or third parties' copyright protected property. Alteration, assignment, distribution and reproduction are forbidden.

LIMITATION OF LIABILITY

The information included in or available through this technical information may include inaccuracies or errors. In no event shall Husqvarna and/or its suppliers be liable for any damages whatsoever, arising out of or in connection with the use of this technical information. Please always refer to the Husqvarna owners and repair manuals for proper instructions or contact the Husqvarna Dealer Services Department. ©2017 Husqvarna Motorcycles North America, Inc. – All rights reserved