

Airstream Service Bulletin

Bulletin Number: 174

Product Line: Airstream Atlas

Subject: Battery Fuse Replacement

Operation Code: **TCSBR8364079**

Labor rate will be .25hrs

It has come to our attention that in certain scenarios the 150-amp fused circuit could potentially fail. This fuse controls 12 volt operation within the coach. Therefore, we are upgrading the fuse to the 200-amp fuse.

The procedure below is for the 2018 Airstream Atlas.

Please contact the Airstream Customer Service office at 937-596-6111 ext. 7401 if parts are needed and they will be sent at no charge.

RANGE OF VEHICLES INVOLVED:

2018 Airstream Atlas built between 11/17/2017 and 2/13/2018


Serial number range: **305459 - 306131**

Note: Because our VINs do not run in a contiguous series, there will be units in the VIN range which will not be affected by this Service Bulletin.


Equipment needed:

- 13mm Socket and Torque Wrench
- 200 amp Fuse (**Part # 512660-200**)

Step 1: Start by accessing the batteries. The compartment is located on the curbside behind the passenger side door. You will need to remove the pin under the compartment and slide the compartment out.



Step 2: Remove the rubber cap on the positive terminal of the rear battery to expose the lug.



Step 3: Using a 13mm wrench or socket, remove the nut holding the positive battery cable, remove the cable and the 150 amp fuse located on the lug.



Step 4: Replace the 150 amp fuse with the 200 amp fuse (**Part # 512660-200**) and re-attach the battery cable and nut. The torque rating for this nut is 75 inch lbs.



Step 5: Close the battery box and re-insert the pin.