



Service Bulletin

File in Section: -

Bulletin No.: 18-NA-127


Date: April, 2018

INFORMATION

Subject: Corrosion and/or White Powdered Build Up On the A/C Lines in the Engine Compartment

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2017	2018				
GMC	Canyon						

Involved Region or Country	North America and NA Export vehicles	
Condition	 5044650 Some customers may comment on corrosion and/or white powder on the A/C lines in the engine compartment.	

Cause	 5044680 This condition may be caused by flux build up during the supplier brazing process of the A/C lines.
Correction	Check and verify that no leaks are found and clean the flux build up using a soft wire brush. Note: DO NOT replace the A/C lines for this condition.

Version	1
Modified	Released April 20, 2018