

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

aimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions
about this Letter, please
submit your inquiry on the
Web using the [WSC Link](#)
on [DTNACconnect](#)

REF #: ICI18-008

Effective: 04/02/2018

Release: 04/02/2018

SUBJECT: SF552 Revised Bulletin

This letter is to inform you that a revised bulletin for Field Service Campaign **SF552 Medium Duty DD5 AC Dryer Hardware Updates** is available on DTNACconnect. Please print and use the revised bulletin for all work under SF552 from this point forward.

REVISIONS: The SF552B/25-SF552-001 kit was built with A9362002870/Belt Tensioner Replacement. **The correct Belt Tensioner Replacement part number is A9362002670.** The 25-SF555-001 kit has been corrected.

For questions concerning the **SF552B certification label**, The DDC contact has changed to Dan Moote (313) 592-5690. The Bulletin has been updated.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNACconnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.