

General Information

Freightliner Custom Chassis Corporation has received reports of leaks at the fill neck on coolant surge tanks on the Walk-In Van and the MB55 Shuttle Bus chassis. The affected surge tank part numbers are VAB 1010093 and VAB 1010096 and have date codes of 4183 to 4189. The date code is located on the surge tank near the caution label. Leaking surge tanks with these part numbers and date codes should be replaced. For surge tank removal and installation instructions, see **Group 20** in the *Shuttle Bus Chassis Workshop Manual* or the *Walk-In Van Chassis Workshop Manual*.

Parts

The replacement surge tank part number is VAB 1010096 and can be ordered through the PDCs.

Warranty

Normal warranty applies. When submitting claims, reference this service bulletin by number in the story of the claim. Use the damage code and repair time information in [Table 1](#). The part number of the surge tank removed from the vehicle should be used as the primary failed part number on the claim.

Damage Code and Repair Time Information			
Damage Code	Operation Number	Description	Time: hours
267-000A05609	267-0010A	Surge Tank Replacement	0.4

Table 1, Damage Code and Repair Time Information