

PRODUCT UPDATE

HT Series Air Springs Dual Sourced

LIT NO: P46010

DATE: July 2018

Hendrickson Trailer Commercial Vehicle Systems announces a change to HT™ Series air springs, C-20127 (replacement number S-20127) and B-4771 (replacement number S-4771).

In February 2018, Hendrickson began using a secondary supplier for S-20127 and S-4771 air springs specified as replacements on HT Series suspensions. Due to the dual-sourcing of these air springs, there are varying visual differences in height, diameter and geometric design in the uninflated state. These variations, however, do not change the fit or function of the air springs, and they continue to meet Hendrickson's stringent quality standards. Additionally, production and aftermarket air spring part numbers are unchanged.

There are no concerns with mixing manufacturers of the same air spring part number on a suspension. The air springs will have the same performance characteristics when inflated. *Example: C-20127 and S-20127 may be mixed on the same suspension.*



Ex: Uninflated height difference of C-20127 Air Springs



Ex: Piston difference of B-4771 Air Springs

As always, Hendrickson is committed to providing world class products and customer service. Please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247) to speak with a customer service representative regarding this update.

Call Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601