

PRODUCT UPDATE

TIREMAAX® PRO Hubcap Assemblies

LIT NO: P56046

DATE: July 2018

Hendrickson Trailer Commercial Vehicle Systems announces a change to TIREMAAX® PRO hubcap assemblies. Currently, all TIREMAAX PRO hubcap castings include a fill port that allows operators to easily add oil to the wheel bearings. This feature is not required when using grease lubricant. Therefore, beginning August 2018, the fill port will no longer be present on TIREMAAX PRO HN and HP grease hubcap assemblies (*see images below*).

Fit and function of the new grease hubcap assemblies remains unchanged. They are reverse compatible and can be used on the same trailer as a grease hubcap with fill port. The part numbers for the hubcap assemblies, associated TIREMAAX kits, and aftermarket hubcap replacement kits will not change, nor does Hendrickson intend to mix revisions on an order.

**Current HN PRO Hubcap Assembly
with Fill Port**



**New HN PRO Hubcap Assembly
without Fill Port**



This change is specific to HN and HP grease hubcap assemblies for TIREMAAX PRO. No changes have been made to the TIREMAAX PRO Extended HP hubcap assemblies (for use with castellated nut) or TIREMAAX CP hubcap assemblies at this time.

As always, Hendrickson is committed to providing world-class products and exceptional customer service. Please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247) to speak with customer service regarding the change.

Call Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601