

**Service Information System**[Previous Screen](#)

Welcome: lanets

◀ Product: NO EQUIPMENT SELECTED  
 Model: NO EQUIPMENT SELECTED  
 Configuration: NO EQUIPMENT SELECTED

**Technical Information Bulletin****Fuel Filter May Leak on Certain 3406, 3412, C9, C9.3, C13, C15, and C18Engines {1260, 1261, 1262}**

Media Number -M0097173-00

Publication Date -2018/08/10

Date Updated -2018/08/10

**Caterpillar: Confidential Yellow**

i07487545

**Fuel Filter May Leak on Certain 3406, 3412, C9, C9.3, C13, C15, and C18Engines {1260, 1261, 1262}**

SMCS - 1260; 1261; 1262

**Articulated Truck**

730C (S/N: TFF1-UP)

730C2 (S/N: 2T41-UP; 2L71-UP)

745C (S/N: TFK1-UP)

**Electric Power Generation**

C13GENSET (S/N: DH41-UP)

**Engine**

3412 (S/N: 38S1-UP)

C13 (S/N: N3F1-UP)

C15 (S/N: KRA1-UP; N5F1-UP)

C18 (S/N: JLE1-UP)

**Excavator**

336E (S/N: YCE1-UP)

336F (S/N: TZA1-UP; RKB1-UP; LTP1-UP; WTZ1-UP)

349E (S/N: RGH1-UP)

349F (S/N: BZ21-UP; HPD1-UP)

352F (S/N: NDC1-UP; YEG1-UP; A9J1-UP)

374F (S/N: DNM1-UP)

**Generator Set**

3406C GEN SET (S/N: C2G1-UP)

C15 GEN SET (S/N: T4A1-UP; C5L1-UP; NAP1-UP)

C18 GEN SET (S/N: LNB1-UP; L8D1-UP; NKM1-UP)

**Industrial Engine**

**C9 INDUSTRIAL (S/N: REH1-UP)**

**C9.3 (S/N: D9N1-UP)**

**Motor Grader**

**120K (S/N: SZN1-UP)**

**120K Series 2 (S/N: SZS1-UP)**

**12K (S/N: JJA1-UP)**

**Off-Highway **Truck**/Tractor**

**770G (S/N: KDH1-UP; ECM1-UP)**

**772G (S/N: KEX1-UP)**

**Track-Type Tractor**

**D6N (S/N: LJR1-UP)**

**D6T (S/N: SMC1-UP; RAD1-UP; KMR1-UP; GCT1-UP; SGT1-UP; HTZ1-UP)**

**D8R (S/N: 9EM1-UP)**

**D8T (S/N: J8B1-UP; FMC1-UP)**

**D9T (S/N: RJS1-UP)**

**Wheel Loader**

**950H (S/N: MXL1-UP)**

**962H (S/N: SSA1-UP)**

**966H (S/N: BJ61-UP; BS61-UP)**

**980M (S/N: KRS1-UP)**

**982M (S/N: F9A1-UP; LRS1-UP; K1Y1-UP)**

**988K (S/N: LWX1-UP; TWX1-UP)**

## Introduction

The problem that is identified below does not have a known permanent solution. Until a permanent solution is known, use the solution that is identified below.

## Problem

---



Illustration 1

g06335724

In certain cases the **1R-0749** Fuel Filter can develop a small leak at the top plate. In most cases if these filters develop a leak the leak will be small and will show shortly after installation.

## Solution



**Do not operate or work on this product unless you have read and understood the instruction and warnings in the relevant Operation and Maintenance Manuals and relevant service literature. Failure to follow the instructions or heed the warnings could result in injury or death. Proper care is your responsibility.**

Inspect and replace with good **1R-0749** Fuel Filter.

Retain failed parts and check "Send It Back" for an open parts return request.

[Private Network For SIS Licensees.](#)