



SERVICE BULLETIN

**CONVENTIONAL AIR CLEANER HOUSING BOOT
DEFORMED**

**GROUP: 0-GENERAL
BULLETIN NO: SB-18-027
DATE: 9-28-2018
REF: HMM-180917-B1**

SUBJECT VEHICLES: 11MY-18MY Conventional Trucks equipped with a J08 engine

Note: This technical service bulletin is provided as technical information and is not authorization for a warrantable repair.

OVERVIEW:

The subject vehicle may experience an appearance concern of the air cleaner housing boot. This deformation does not affect function. The air cleaner housing boot has been changed, removing the ribs on the front side to prevent deformation. This boot can be replaced separately from the air cleaner housing if replacement is desired.



PARTS:


Part Number	Part Description	Quantity
17714EV030	Air Cleaner Housing Boot	1
17783EV010	Retainer Pins	As Needed (4 maximum)

BEFORE YOU BEGIN:

- Read and understand all instructions and procedures before you begin the work.
- Read and follow all **WARNINGS** and **NOTICES** set forth in this publication. These alerts help to avoid damage to components, serious personal injury, or both.
- Park the vehicle on a flat, level and solid surface.
- Place the gear shift lever in "Neutral" or "Park".
- Apply the parking brake firmly and confirm parking brake activation.
- Turn off the engine and remove the key from the ignition switch.
- Always wear safety glasses or goggles to protect your eyes.
- Place wheel chocks in front of and behind all the wheels to prevent the vehicle from moving

VEHICLE PREPARATION:

1. Park the vehicle on a flat, level and solid surface.



2. Confirm the engine is stopped, the ignition switch is in the off (LOCK) position, and the key is removed.



3. Apply the parking brake



4. Chock all of the wheels.



REPAIR PROCEDURE:

1. Release the hood latches on both sides of the vehicle.



2. Raise the hood fully.



3. Using a suitable trim tool, carefully remove the four (4) retaining pins securing the air cleaner boot. Note that the photo shows two of the four pins, the remaining two pins are on the opposite side of the housing. Retain these pins for reassembly, then remove and discard the old air cleaner housing boot.



4. Place the new boot (17714-EV030) on the air cleaner housing. Make certain the inner lip hooks over the edge of the air cleaner housing on all four sides.

NOTICE: There are notches on the side of the air cleaner boot to indicate proper orientation



5. Press the retaining pins removed in step 3 back into the air cleaner housing to secure the new air cleaner housing boot. Note that the photo shows two of the four pins, the remaining two pins are on the opposite side of the housing.

NOTICE: If these retaining pins are damaged, replace using part number 17783-EV010.



6. Lower the hood and engage the hood latches on both sides of the vehicle.



FINAL INSPECTION:

1. To complete this TSB review and confirm the following:
 - The new air cleaner housing boot is installed in the correct orientation
 - All four retaining pins are fully seated
 - Both hood latches are fully engaged

CLAIM APPLICATION:

Reimbursable in accordance within the terms and policies of the Hino limited warranties.

Air Cleaner Housing Boot Replacement:

- a) Labor charge: 0.3 Hour
- b) Warranty code: 11119
- c) Trouble code: 55
- d) Operation code: 11150AOT
- e) Original failed part: 17714-EV010

