

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2018090001, October 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model G-Class (463 platform)

Model Year 2017 and 2018

Replace sensor for oil level display

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY17-18 G-Class (463 platform) vehicles the oil level sensor may not meet production specifications, which could lead to erroneous high oil level error messages. An authorized Mercedes-Benz dealer will replace the oil level sensor for the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 1031 vehicles are affected.

Order No. P-SC-2018090001

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Procedure

1. Replace sensor for oil level display.

 For basic data, see **AR18.40-P-5116MNA**.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Sensor	A 177 905 01 00	100%

Warranty Information

Operation: Replace sensor for oil level display(02-2399)

Damage Code	Operation Number	Labor Time (hrs.)
18 901 32 7	02-2399	1.0

Note

Operation Number labor times are subject to change.