

H[®] PRODUCT UPDATE


ULTRAA-K[®] Air Spring Change

LIT NO: P36029

DATE: December 2018

Hendrickson Trailer Commercial Vehicle Systems announces a change to ULTRAA-K[®] air springs. Beginning late Q1 2019, new production ULTRAA-K[®] air slider suspension systems will be equipped with new air springs. The new air spring, featuring a new part number, provides optimized ride dynamics and improved ride quality. It also has a quicker air-up time.

The graphic below illustrates the visual differences between the new production air spring, C-38000, and the current production air spring, C-34733. Please note the stud location of both air springs remains the same.



***Note: These air springs should NOT be mixed on the same air slider suspension system.**

Implementation

This change impacts all new ULTRAA-K models and will be phased in late Q1 2019. The production air spring part number will change from C-34733 (service part number S-34733) to C-38000 (service part number S-38000). ULTRAA-K model numbers will also change.

Replacement Parts

Although both the current and new air spring designs will fit the suspension beam identically, they operate at different pressures. Therefore, to maintain proper performance and avoid premature wear, they should **NOT** be mixed on the same slider suspension system. Refer to the chart below to determine which air spring to use when replacing ULTRAA-K air springs.

Replacement Parts List		
Air Spring(s) on Slider	Replacing Only One Air Spring	Replacing All Air Springs
C-38000	Use S-38000	Use all S-38000
C-34733	Use S-34733	Use either all S-34733 or all S-38000

As always, Hendrickson is committed to supplying innovative products that enhance the value, serviceability and lifespan of your vehicles. Please contact us at 1-866-RIDEAIR (743-3247) or visit www.hendrickson-intl.com for more information.

Call Hendrickson at **330.489.0045** or **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601