

GPOP - Issue Review System

Part Number: 68414414A\$, 68322864A\$

Part Description: CAMERA (Rear)

Issue Description: Rear camera screen blank/blue/inop

Please ensure the radio is at the latest software level prior to replacing the rear camera.

After updating the radio, the system requires two key cycles to function properly. If the camera is inoperative after the radio update, proceed with repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
