

A/C System Non-Functional / Noise In Engine Compartment

Topic number	LI83.55-P-071130
Version	1
Function group	83.55 A/C compressor
Date	03-26-2020
Validity	Model series 177 and model series 118 with M139
Reason for change	
Reason for block	

Complaint:

A/C system nonfunctional and/or noise from engine compartment area.

Cause:

Under analysis.

Remedy:

If there are any problems with the A/C system and/or if the refrigerant compressor is damaged, create a PTSS case.

Provide the following information for the case:

- Customer complaint
- Workshop findings
- Quick test and, where applicable, control unit log
- Damaged component parts (including representative photos)
- Refrigerant fill level in event of problem
- Can a leakage be detected in the system?

Symptoms
Power generation / Engine noise / Noise
Body / Air conditioning / Air conditioning / Insufficient cooling output
Power generation / Mechanical engine components / V-belt / Noise
Body / Air conditioning / Air conditioning / Noise

Validity		
Vehicle	Engine	Transmission
<177>	139	*
CLA (118)	139	*

