

CUSTOMER STATES LP REGULATOR LEAKING, REMOVED REGULATOR AND COVER, INSTALLED NEW REGULATOR AND NEW PINS TO HOLD COVER IN PLACE, FILLED WITH 5.8 GALLS LP AND TESTED FOR LEAKS. WORKING AS DESIGNED.
(LABOR 1.20)

1.0 approved maximum. Please contact Fairview fittings at 800-688-4088 for warranty part. This will now be part of customer's maintenance because regulators are only covered 1 year from DOP because it's a wearable item.