



Technical Journal

TITLE:

Seat belt catch, foreign objectsREF NO:
TJ 19383.7.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2020-07-10STATUS DATE:
2020-07-16FUNC GROUP:
8843FUNC DESC:
Catch for safety belt

Page 1 of 2

“Right first time in Time”

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
124							2007-2016		-	0-0
134							2011-9999		-	0-0
135							2008-2016		-	0-0
136							2008-2016		-	0-0
137							2016-9999		-	0-0
138							2014-9999		-	0-0
144							2009-2015		-	0-0
155							2011-9999		-	0-0
156							2009-9999		-	0-0
157							2015-9999		-	0-0
184							1999-2006		-	0-0
224							2019-9999		-	0-0
225							2019-9999		-	0-0
227							2019-9999		-	0-0
234							2017-9999		-	0-0
235							2017-9999		-	0-0
236							2017-9999		-	0-0
238							2018-9999		-	0-0
246							2018-9999		-	0-0
256							2016-9999		-	0-0
275							2003-2016		-	0-0



Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
285							2000-2008		-	0-0
295							2001-2007		-	0-0
384							2001-2009		-	0-0
525							2013-9999		-	0-0
526							2013-9999		-	0-0
533							2007-2013		-	0-0
536							2019-9999		-	0-0
542							2006-2013		-	0-0
544							2004-2012		-	0-0
545							2004-2012		-	0-0

CSC Customer Symptom Codes

Code	Description
VU	Seat belt and other safety systems/Buckle latching problems

VST Operation Number

VST Operation Number	Description
99921-2	General according to TJ

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

When analyzing replaced seat belt catches, we have found catches with coins, candy, nuts etc inside, causing the problem.

* Several vehicle types has been added.

* VST Operation No. updated.

SERVICE:

Before replacement the belt catch must be checked for any kind of foreign objects inside. If there are objects inside the belt catch try to carefully remove the object with a vacuum cleaner or compressed air. Do not use a screwdriver or similar. Then check that the function of the belt catch is ok.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use the attached VST OP number.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8843.