



SERVICE CAMPAIGN FOR:

TPMS High Cluster Reading

DESCRIPTION:

The instrument cluster is displaying the incorrect tire pressure,

CORRECTIVE ACTION:

Re-program Instrument Cluster, MID140

UCHP SCC CODE: S7528

EXPIRATION DATE: 9/30/2021

CAUSAL PART: 85102457

PARTS MARKUP: na

UCHP LABOR CODE:

PARTS:

Labor Code - Description - Hours	Parts List - Description - Quantities
3810-22-03-03 MID 140 Control Unit, Programming .4hrs	na

FOR MORE INFORMATION CONTACT:

Chris Mann chris.mann@volvo.com