

have two new 2020 western stars...



[Grant Overton](#) 124 posts since Nov 14, 2014

have two new 2020 western stars LT2514 + LR5411 have loose rear spring shackle bushings in the springs causing steer axle to shift on pins, pin bushings just float in spring eye, any suggestions besides replacing the spring with new Oct 2, 2020 3:41 PM

brand new truck in service sept 1 2020 8000 km need info on repair vs replace spring to stop spring from shifting on the pin bushings?



[Morgan Barnes](#) 17 posts since Mar 8, 2016

Re: have two new 2020 western stars LT2514 + LR5411 have loose rear spring shackle bushings in the springs causing steer axle to shift on pins, pin bushings just float in spring eye, any suggestions besides replacing the spring with new Oct 4, 2020 12:02 AM

I WOULD DOUBLE CHECK IN PARTS PRO THAT YOUR UNITS GOT THE CORRECT BUSHINGS INSTALLED. WOULD HAVE TO REMOVE 1 OF THE BUSHINGS WITHOUT DAMAGING IT TO CONFIRM.



[Scott Trippel](#) 3,958 posts since Dec 13, 2014

Re: have two new 2020 western stars LT2514 + LR5411 have loose rear spring shackle bushings in the springs causing steer axle to shift on pins, pin bushings just float in spring eye, any suggestions besides replacing the spring with new Oct 5, 2020 1:42 PM

You need to replace the springs Grant.

This was a problem we saw a lot of prior to 2010 maybe even older. We would spot weld the bushings in the springs so they would not slide. Be being warranty they should be replaced. I ran the bushing in Owl an cause as loose and it starts a claim



[Grant Overton](#) 124 posts since Nov 14, 2014

Re: have two new 2020 western stars LT2514 + LR5411 have loose rear spring shackle bushings in the springs causing steer axle to shift on pins, pin bushings just float in spring eye, any suggestions besides replacing the spring with new Oct 5, 2020 3:26 PM

thanks Scott .



[Scott Trippel](#) 3,958 posts since Dec 13, 2014

Re: have two new 2020 western stars LT2514 + LR5411 have loose rear spring shackle bushings in the springs causing steer axle to shift on pins, pin bushings just float in spring eye, any suggestions besides replacing the spring with new Oct 5, 2020 6:22 PM

Any time Grant