

IMPORTANT CUSTOMER SATISFACTION REMINDER

DL1000A/AA ENGINE CONTROL MODULE (ECM)



P.O. Box 1100
Brea CA 92822-1100

Vin#

Campaign AU-R6

Presorted
First Class Mail
U.S. Postage

PAID

Torrance, CA
Permit No. 1



##

2

IMPORTANT CUSTOMER SATISFACTION REMINDER

SIXTH REMINDER - ACTION REQUIRED

1 WHY HAVE YOU RECEIVED THIS NOTICE?

In October 2017, owners of select 2014 and 2015 DL 1000/A/AA models were notified of a service campaign to replace the ECM on affected motorcycles. Suzuki has revised the programming of the engine control module and parts are available to perform this important customer satisfaction service.

2 WHAT SHOULD YOU DO?

Please make an appointment to have your vehicle repaired **free of charge** at any Suzuki Dealer. **To locate your nearest Suzuki Dealer, go to www.suzukicycles.com and click on Find a Dealer at the top of the web page.** Provide the Vehicle Identification Number (VIN) from the front of this card to your Suzuki Dealer.

The engine control module (ECM) has been revised to prevent engine stalling when decelerating to a stop.

We care about your safety and ask that you immediately make arrangements to have this **FREE** repair performed.

Thank you for being a Suzuki Customer.

Suzuki Motor of America, Inc.



To find your nearest Suzuki Dealer, go to www.suzukicycles.com and click on **Find a Dealer** at the top of the web page.

If you're having trouble having this repair completed, contact Customer Support at **1.714.572.1490** Monday through Friday 8 a.m. to 4 p.m.. PST