

ONTOUR 2.0

CUSTOMER STATES - That the roof a/c is leaking after about 15 minutes of it being turned on. It seem to be coming out of the front vent (movable) closest to the front of the coach, and then also from the very center (movable) vent. See Barbie.

This is an leak that is happening on the inside of the unit. Customer states that it leaks while on, but pours out more so when it is shut off.

Parts

Part #	Qty	Description
08-0062	1.00	A/C GASKET KIT 14IN X 14I

Labor

Description
Diagnosis
Remove, clean, replace, seal, and wrap up.

ONTOUR 2.0

When we purchased our Ontour 2.0 on Sept. 9th, we noticed a problem with the air conditioner during our walkthrough. Evidently, the unit had frozen up, and water poured from the AC unit into the van when the unit was turned off. The service department determined that the control module needed to be replaced. The module has nothing to do with this. The AC needs to be resealed. Also check the AC gasket kit 14 inch x 14 inch part 08-0062 if this needs to be replaced. Also when running AC should always be on AC FAN HIGH