

cgw lost communication with cpc



[Donald Sullivan](#) 45 posts since Nov 14, 2017

cgw lost communication with cpc Jan 18, 2021 11:03 PM

2020 new Cascadia. was doing recall d20m8 acm software update. after updating software on acm, perform a icu auto configuration routine. now the cpc, mcm, acm, and tcm will not connect. faults log are 524000/31, 524017/31, 523021/31, and 523023/31. went to perform trouble shooting on 524000/31. pins that were called out on trouble shooting from dl8 did not match the truck. did manage to fine can network. check resistance value are 60.6 ohms. wanted to check voltage at x5 pin 3 and 8 also pins 9 and 6. x5 connector only has 3 pins not 4. getting 12 volts on 2 of 3 wires. specs in trouble shooting calls for 2.5 volts but hard to believe trouble shooting with incorrect pin outs in troubleshooting. can not find schematics for harness or troubleshooting on psl. has any one else run into this.

last four of vin is mf9890



[Scott Trippel](#) 4,057 posts since Dec 13, 2014

Re: cgw lost communication with cpc Jan 18, 2021 11:08 PM

Look for schems in Parts Pro or Exceleator



[Donald Sullivan](#) 45 posts since Nov 14, 2017

Re: cgw lost communication with cpc Jan 19, 2021 1:29 PM

Truck fix. Was doing some digging on issues with recall d20m8 and found that some truck after programing there acm would loose all data. connected cpc manually and reflash cpc. after flashing cpc all powertrain devices connected. program module to software level needed from recall and perform icu auto configuration. all faults went inactive.



[Donald Sullivan](#) 45 posts since Nov 14, 2017

Re: cgw lost communication with cpc Jan 19, 2021 1:31 PM

not sure how or why but cpc lost its programming after doing icu auto configuration the first time.