



Service Literature

To: General Managers
Service Managers
Service Technicians
Warranty Managers

Region: ☒ U.S.
☒ CAN

Bulletin: SLV21-002
Date: February 28, 2021

Valid to: N/A

Action Required? ☒ Yes ☐ No

From: Volvo Trucks – Service

Subject: Service Literature Published and Released in February, 2021

The following summarizes the service literature that has been published and/or revised for the month.

SERVICE NEWS

BULLETIN #	TITLE	COMMENTS
SNV21-002	Pick-Up and Delivery Service	New
SNV21-003	Dealer Afterhours Support	New

TOOL BULLETIN

BULLETIN #	TITLE	COMMENTS
STB21-001V	Preliminary Electro Mobility Special Tools List	New

FIELD SERVICE BULLETIN

BULLETIN #	TITLE	COMMENTS
	None Issued	

SERVICE PROGRAM

BULLETIN #	TITLE	COMMENTS
S7556	Turbo Compound Replacement	New
S7558	VECU Active code and no MIL Lights	New

RECALLS

BULLETIN #	TITLE	COMMENTS
C6621	RVXX2006, Norgren Collet Inspection/Replacement	Revision



(CBR) CASE BASED REASONING

NEW SOLUTIONS

SOLUTION #	TITLE
CBR-2079	Diagnostic Trouble Code (DTC) U008088 - US17+OBD16 Emissions And Newer
CBR-2080	Diagnostic Trouble Code (DTC) P2AB047 - US14+OBD16 Emissions And Newer
CBR-2095	Premium Tech Tool Version 2.8.* - Operation 1700-08-03-39: Program Electronic Control Unit
CBR-2094	Infotainment System - Volume Drop During A Bluetooth Call

UPDATED SOLUTIONS

SOLUTION	TITLE	COMMENTS
CBR-133	Volvo Chassis - IMPORTANT INFORMATION: READ PRIOR TO USING THE BULLETIN Field Service Bulletin (FSB) 213-002 Exhaust Rocker Compression Brake Piston, Repair; Repair For Exhaust Rocker Pistons Volvo Engine Brake (VCB, VEB)	Removed the build date reference and D12.
CBR-107	Selective Catalytic Reduction (SCR) Efficiency And NOx Sensor Diagnostic Trouble Codes (DTC) P225C, P225E, P221A and P2201: NOx Sensor Diagnostic Information TO BE USED BEFORE SENSOR REPLACEMENT - OBD13 And Newer Emissions	Updated formatting.
CBR-2051	Volvo Chassis - Air Conditioning (A/C) Performance Chart - Trucks Built After January 2019	Updated tags for improved searchability. Rebuilt temperature/pressure table and added metric measurements.
CBR-2085	Volvo Chassis - Diagnostic Code (DTC) B105254 Active And Unable To Be Cleared - Vehicles Manufactured On Or After 1 January 2021	Added link to Service Campaign S7558.
CBR-277	Volvo Chassis - Particulate Matter (PM) Sensor Diagnostic Trouble Codes (DTC) Illuminating The Malfunction Indicator Lamp (MIL); Tech Tip TT-014-2016 - US14+OBD16, US17+OBD16 And Newer Emissions, Common Model Year 2017 And Newer	Fixed reference to old CBR solution number with updated format.
CBR-2042	Volvo Chassis - ABS Controller Programming	Edited tagging to improve searchability.