

Concern: Dealer States during the PDI when testing when testing the kitchen faucet it flooded the cabinet underneath.

Cause: Found that when the faucet was installed at the factory the pull up hose was not properly connected to the faucet feed causing it to blow off under pressure and blow water everywhere.

Solution: Remove drawers and shelf to access. Dry up water in cabinet area. Properly connect sprayer hose back to faucet quick connect. Test faucet operation and check for leaks. Reinstall shelf and drawers.

Requested Time 1.0 0.50 approved. You only need to remove the 2 drawers and the line is already there.