

GPOP - Issue Review System

Part Number: 05183147AA

Part Description: Rear HVAC blower

Issue Description: Noise coming from rear HVAC blower due to interference between the blower cage and the HVAC case. Please call one of these two individuals before replacing the blower. Sean Hixenbaugh at cell 973-673-7703, or Mike Grzybowski at cell 248-635-5340. (If it is an interference issue, then the entire unit will have to be removed and returned for analysis.)~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
