

2021 Plateau

1. Concern: The couch button on the front control panel will not operate for the rear couch

Cause: Component failure. The touch panel still did not function the back sofa. The back touch panel does work to move the power sofa.

Correction: R & R control panel

Time: 1 hour 0.50 approved. This panel is just plug n' play. Please contact Spyder Controls at 866-919-9092 and look for Christian for warranty. They will send you a new touch panel no charge.