

May 5, 2021

Product Change Notice - Protective rubber overmold added to In-Wall Slide-out motors


Dear Valued Customer:

Please be advised, as part of continued improvement to overall motor durability, Lippert intends to add a protective rubber overmold to the 500:1 and 300:1 In-Wall Slide-out motors where the wire exits the motor.

Lippert will also add non-conformal coating to the PCB to protect the electrical components from corrosion.

There is no change in function, operation or installation with the added rubber overmold and coating change. There is no price change and no part number change. This will be a running change.

500:1




Protective
overmold



Current

New

300:1



Protective
overmold



Current

New

Black wrap on
sample only

If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

Mason Ogle

VP of RV Sales

Lippert Components, Inc.

c: 574.849.1742

mogle@lci1.com

Frequently Asked Questions:

- 1. Will a new part number be required?** No, there is no new part number.
- 2. Does the price change for the item?** No, there is no price change.
- 3. Is the new part wholly interchangeable with the previous version of the part?** Yes, the motors are interchangeable.
- 4. Does the customer need to replace inventory?** No, the change will be made on a running basis.