



Oil Leak At Turbo Oil Supply Line And Fitting Connection - 11L





> Internal Content

Oil leaks from the VGT turbo oil supply line and/or the supply line connection have been found on some 11L engines.

Inspected for the source of the leak and select the correct scenario below.

- **Scenario A:** If leaking between turbo fitting and supply line is confirmed, replace both fitting and line.
- **Scenario B:** If Leaking from fitting only is confirmed, supply line is in good shape, and truck is built before clean date (1/15/21), replace the fitting only.
- **Scenario C:** If built after the clean point (1/15/21) and leak is confirmed from supply line, replace supply line only.



Required Parts

Part Number	Descrtiption	QTY
984891	Fitting	1
21400638	Oil Supply Line	1

 Tags

oil leak

turbo oil leak

Related links and attachments

No links or attachments available

 Feedback

[Give feedback](#)

to help improve the content of this article