



Mack Chassis - SNM16-031 US'14 (GHG) MP8 Two Piece Valve Cover (Corroded Screws)



> **Internal Content**

For more information refer to the SNM16-031 US'14 (GHG) MP8 Two Piece Valve Cover (Corroded Screws) found in the Trucks Dealer Portal - eMedia Center or click [here](#).



Tags [k15742667](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article

MACK TRUCKS

Service News



To: U.S. and Canada Mack General Managers
U.S. and Canada Mack Service Managers
U.S. and Canada Mack Service Technicians
U.S. and Canada Mack Warranty Managers

Bulletin: SNM16-031
Date: September 12, 2016
Valid to: Until Further Notice
Replaces: N/A
Action Required? **Yes**

From: Greg Holderfield – Director, Product Reliability

Subject: US'14 (GHG) MP8 Two Piece Valve Cover (Corroded Screws)

An improved screw (Part # 22806270) is being released to prevent corrosion on the stem of the screw and threads. If corrosion has occurred replacement of all screws is required. If you encounter a screw that has corroded or seized, make sure the crush sleeve inserts in the lower cover remain secure during repairs. **Failure to confirm that all sleeves remain in lower cover could lead to engine damage.** The crush sleeves are not offered as a spare part at this time, however we are in the process of getting sleeves released as a spare part.

