



SIB 72 02 13

2021-09-08

Lower Belt Buckle for Front or Rear Seat May Not Function

This Service Information Bulletin (Revision 2) replaces SI B72 02 13 **dated December 2013**.

What's New (Specific text highlighted):

- Models added
- Warranty updated

MODEL

all models thru current production

SITUATION

The customer may report one or more of the following situations:

1. Safety belt will not buckle intermittently.
2. The lower belt buckle button is stiff when releasing or connecting the safety belt.
3. The check control message is displayed prompting the customer to buckle the safety belt while the seat is occupied.

CAUSE

Foreign objects entered into the lower safety belt buckle causes mechanical failure and damage to the switch (paper clip, paper, food, soda, water, coins...)

PROCEDURE



1. Inspect the lower safety belt buckle and release button for any foreign objects (paper, coins, food etc).
2. Inspect the lower safety belt buckle and release button for any signs of spillage (coffee, soda etc) as shown in photo.

WARRANTY INFORMATION

This Service Information Bulletin provides technical, diagnostic, and repair-related information.

Damage and/or issues caused by outside influences are not covered under the BMW limited warranties.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections