


MULTI-MODEL **EXTERIOR TRIM HEAT DAMAGE**

Some vehicles may experience exterior trim heat damage when parked near a glass building. This may be caused by the sun's reflection.



If a building creates enough of a curve with a series of flat windows, which act like mirrors, the reflections all converge at one point, focusing and concentrating the light onto the street below.

Warranty Compliance Note:

Vehicle repairs for this concern are not covered under Mazda's warranty policy.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2015 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive 10,000 Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.