Technical Service Bulletin

Technical Service Bulletin: TSB220182	**Released Date**: 30-Aug-2022
Engine Oil Pressure Switch Replacement Part Number	

Engine Oil Pressure Switch Replacement Part Number

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- B4.0 CM2620 B154B
- B4.5 CM2350 B129B
- B4.5 CM2350 B146C
- B4.5 CM2620 B158B
- B4.5 CM2620 B180B
- B5.6 CM2670 B152B
- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2450 B155B
- B6.7 CM2670 B153B
- D4.0 CM2620 D103B
- D4.5 CM2620 D104B
- F3.8 CM2350 F120B
- F3.8 CM2350 F128C
- F3.8 CM2350 F133C
- F3.8 CM2620 F137B
- F4.5 CM2620 F139B
- F4.5 CM2620 F141C
- ISB CM2150
- ISB CM2150 E
- ISB/ISD4.5 CM2150 B119
- ISB/ISD4.5 CM2150 SN
- ISB/ISD6.7 CM2150 B120

- ISB/ISD6.7 CM2150 SN
- ISB/ISD6.7 CM2880 B126
- ISB3.9 CM2220 B107
- ISB4.5 CM2150
- ISB4.5 CM2350 B104
- ISB5.9 CM2150 B111
- ISB5.9 CM2880 B110
- ISB5.9 CM2880 B140
- ISB5.9 CM2880 B149
- ISB6.7 CM2250
- ISB6.7 CM2350 B101
- ISB6.7 CM2350 B103
- ISBE CM2150
- ISBE4 CM850
- ISF2.8 CM2220
- ISF2.8 CM2220 AN
- ISF2.8 CM2220 EC
- ISF2.8 CM2220 ECF2
- ISF2.8 CM2220 F101
- ISF2.8 CM2220 F121
- ISF2.8 CM2220 F122
- ISF2.8 CM2220 IAN
- ISF3.8 CM2220
- ISF3.8 CM2220 AN
- ISF3.8 CM2220 F103
- ISF3.8 CM2220 F110
- ISF3.8 CM2220 F116
- ISF3.8 CM2220 F134B
- ISF3.8 CM2220 IAN
- ISF3.8 CM2350 F109
- ISF4.5 CM2220 F123
- ISL CM2150
- ISL CM850
- ISL G CM2180
- ISL9 CM2150 SN
- ISL9 CM2350 L101
- ISLE4 CM850
- QSB (Komatsu)
- QSB3.3 CM2150
- QSB3.3 CM2250 EC
- QSB4.5 CM2150 B108
- QSB4.5 CM2250 EC

- QSB4.5 CM2350 B106
- QSB4.5 CM850(CM2850)
- QSB6.7 CM2150 B109
- QSB6.7 CM2250
- QSB6.7 CM2250 EC
- QSB6.7 CM2350 B105
- QSB6.7 CM2350 B130
- QSB6.7 CM850(CM2850)
- QSB7 CM2880 B117
- QSC8.3 CM850(CM2850)
- QSF3.8 CM2350 F107
- QSF3.8 CM2350 F118
- QSF3.8 CM2350 F119
- QSF3.8 CM2880 F112
- QSL9 CM2250
- QSL9 CM2350 L102
- QSL9 CM850(CM2850)

Description of Change

This document identifies the correct service replacement part number for the engine oil pressure switch.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Switch, Pressure	4076930	No	Yes	5677803
Switch, Pressure	5677544	No	Yes	5677803

Production Status

Implemented for production. See Table 2.

Table 2, Production Information

ESN First	Build Date[1]	Plant
74952413	20 May 2022	Rocky Mount Engine Plant

[1]Engine build date can be found on the engine dataplate.

Document History

Date	Details
2022-8-29	Module Created

Last Modified: 30-Aug-2022

https://cst.cummins.com http://edsprod.cummins.com https://gpst.cummins.com
https://quickserve.cummins.com https://parts.cummins.com https://store.cummins.com
https://wwsps.cummins.com https://access.cummins.com https://commerce.cummins.com
https://qsservices.cummins.com https://webparts.cummins.com https://qsservices.cummins.com
https://adminportal.cummins.com 0sp4N000000PGNq https://cumminscommerce.force.com
https://mylogin.cummins.com/web/idp/login