

2022 Rekon

1. This customer has developed holes in screen along what looks like fold lines. Looking for warranty auth to resolve this. 1.0 approved. Sending screen under warranty.