



Bulletin No.: PIT6185
Published date: 06/11/2024

Preliminary Information

PIT6185 Forward Collision Alert / Automatic Emergency Braking (AEB) / Front Pedestrian Alert Inoperative with Forward Collision Icon Lamp On and No DTCs Present

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	All
GMC	Sierra 2500HD/3500HD	2024	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	KGU (Universal Vehicle Module) & VYU (Snow Plow Prep / Camper Package)
Condition	Some customers may comment that Forward Collision Alert, Automatic Emergency Braking, and Front Pedestrian Alert are inoperative and the AEB forward collision icon lamp is illuminated in the cluster. No DTCs will be present and Lane Departure Warning, Adaptive Cruise, and Auto High Beam Assist (Intellibeam) will all be functional.
Cause	The cause of the condition is a software anomaly that Engineering is aware of.

Correction:

Engineering is currently aware of this concern and working on a fix. Do not replace any parts at this time.

Version History

Version	1
Modified	06/11/2024 - Created on.

