



SSM 54594 2023-2026 F-Super Duty - Rain Sensitive Wipers Settings Will Not Change From Center Touch Screen And/Or Heated Steering Wheel Inoperative After A Remote Start Event

Some 2023-2026 F-Super Duty vehicles may exhibit rain sensitive wipers (if equipped) settings that do not change when selected in the center touch screen. Vehicles may also exhibit an inoperative heated steering wheel (if equipped) after a remote start event. This may be due to the software in the steering column control module (SCCM). To correct the condition, reprogram the SCCM using the latest software version of the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 3F791 and labor operations 12651D and 12651D4.